

100 Lemon Peel Way Anytown, FL. 55555

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 1 of 48



## **Recommend Maintenance Summary**

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

#### **Lots and Grounds**

- 1. Driveway: Observed The driveway has settled and heaved. This is a possible trip hazard. I recommend contacting a contractor for repair.
- 2. Walks: Observed There are bricks have settled. This is a possible trip hazard. I recommend contacting a local landscape contractor for repair. This is a potential safety issue.

#### Bathroom

3. Bathroom Shower/Surround: Observed - The shower door sticks and is difficult to operate. I recommend contacting a local glass company for repair.

#### Living Space

4. Living Space Windows: Inspected - The handle is loose. I recommend contacting a licensed handyman for repair.

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 2 of 48



## Repair/Replace Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

#### Lots and Grounds

1. Porch: Observed - There is a missing brick at the column. I recommend contacting a licensed handyman for repair.

#### Exterior

- 2. Door Bell: Obsreved The doorbell is not working. I recommend contacting a licensed handyman for repair.
- 3. Exterior Lighting: Observed The light fixture was not working at the time of inspection. This may be a burned out bulb. Recommend replacing the bulb and if this does not cure the problem recommend contacting a licensed electrician for repair.
- 4. Exterior Electric Outlets: The GFI outlet was not working at the time of inspection. The cover was missing. The moisture cover is missing. I recommend contacting a licensed electrician for repair.

#### Air Conditioning

- 5. Pad Mounted AC System A/C System Operation: Observed The AC is not cooling. The minimum temperature differential should be at least 15 degrees. Recommend contacting a local HVAC contractor for repair.
- 6. Pad Mounted AC System Exterior Unit: Pad mounted The AC is not cooling. The minimum temperature differential should be at least 15 degrees. I recommend contacting a local HVAC contractor for repair.
- 7. Cooling/Heating Temperature: Observed The AC is not cooling. The minimum temperature differential should be at least 15 degrees. I recommend contacting a local HVAC contractor for repair.
- 8. Filters: Observed The filter is dirty and should be changed. I recommend contacting a licensed handyman to install a new filter. I recommend replacing the filter as necessary in the future.

#### Plumbing

- 9. Laundry Room, Closet Water Heater Tank Condition: Inspected There is rust at the top of the tank. I recommend contacting a licensed plumber for further evaluation.
- 10. Laundry Room, Closet Water Heater Plumbing Lines: Observed There is corrosion at the top of the fittings. I recommend contacting a licensed plumber for further evaluation.

#### **Attic**

11. Attic Access: Inspected - The pull down steps in the master bedroom is missing appropriate hardware. I recommend contacting a licensed handy man to replace. This is a safety issue.

#### Kitchen

- 12. Kitchen Stove & Oven: DCS The control panel is not working. There is a missing lens cap on the control knob. I recommend contacting an appliance repair company for repair.
- 13. Kitchen Ice Maker: Obsreved
- 14. Kitchen Lighting: Observed The light is. out

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 3 of 48



## Repair/Replace Summary (Continued)

#### Bathroom

- 15. Bathroom Ceiling: Observed There is a water stain at the vent and closet ceiling. This may have been caused by the air handler and condensation at the vent. I recommend monitoring.
- 16. Bathroom Lighting: Observed The light is out. This may be a burned out bulb. I recommend bulb replacement first. If that does not cure the problem I recommend contacting a licensed electrician for repair.
- 17. Bathroom Spa Tub/Surround: Observed There is no water pressure at the tub spout. I recommend contacting a licensed plumber for repair.
- 18. Bathroom Lighting: Observed The light is out.
- 19. Bathroom Tub/Surround: Observed There was no water at the main sower head. I recommend contacting a licensed plumber for repair.
- 20. Half Bathroom Faucets/Traps: Observed There is a broken stop and mechanism. I recommend contacting a licensed plumber for repair.
- 21. Half Bathroom Electrical: Inspected The ground fault outlet is not working. I recommend contacting a licensed electrician for repair.
- 22. Half Bathroom Lighting The lights are out.
- 23. Half Bathroom Ventilation: The vent fan is not working. I recommend contacting a licensed electrician for repair.

#### Bedroom

24. Bedroom Windows: Inspected - The crank mechanism is stripped. I recommend contacting a licensed handyman for repair.

#### Living Space

- 25. Living Space Lighting: Observed The light fixture does not work. This may be a burned out bulb.. Recommend replacing the bulbs. If this does not cure the problem recommend contacting a licensed electrician for repair.
- 26. Living Space Lighting: Inspected The ceiling light is out.
- 27. Living Space Lighting: Observed The light is out.
- 28. Living Space Plumbing: The disposal does not work. I recommend contacting a licensed plumber for repair.
- 29. Living Space Lighting: Inspected The light is out.
- 30. Living Space Windows: Inspected The crank mechanism is stripped. I recommend contacting a licensed handyman for repair.

The window is missing the screen. I recommend contacting a local window company for replacement.

#### Laundry Room/Area

31. Laundry Room/Area Doors: Inspected - The door latch is not engaging. I recommend contacting a licensed handyman for repair.

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 4 of 48



### **Table of Contents**

Definitions	5
General Information	5
Roof	6
Structure	8
Lots and Grounds	9
Exterior	11
Garage/Carport	13
Air Conditioning	13
Plumbing	18
Electrical	22
Attic	26
Fireplace/Wood Stove	27
Kitchen	28
Bathroom	32
Bedroom	38
Living Space	41
Laundry Room/Area	47

11:54 November 04, 2016



Mr. John Smith 100 Lemon Peel Way Page 5 of 48

#### **Definitions**

STERLING HOME INSPECTION SERVICES, INC.

Because of the visual nature of this home inspection, it is not possible to inspect or report on conditions in areas that are inaccessible, obstructed, or concealed. We can only address those areas that are readily accessible at the time of the inspection. The inspector is not required, and should not be expected, to move furnishings or other items during the inspection, disassemble equipment or open wall coverings. A home inspection is a "snapshot" of the home at the time of the inspection; it is designed to educate a buyer about the home, not to replace the obligation of a home seller to disclose known defects.

A home inspection is not a guarantee or warranty of the condition of the home or property; neither is it a guarantee that conditions will change in the future.

We strongly recommend that the buyer perform a thorough pre-closing walk-through inspection in order to confirm the condition of the house, systems and appliances, and to check areas that may have been obstructed from view at the time of the home inspection.

Observed Functional with no obvious signs of defect.

Cosmetic Items that are decorative or superficial and do not pose any structural issues in the opinion of the

inspector. Interpretation of the rating as to the contract should be determined by others, not the

inspector or inspection company.

Recommend Maintenance This describes areas that the inspector is recommending maintenance to be performed to allow the

item to perform with better efficiency and safety. The item is working at the time of the inspection

however maintenance needs to be performed.

Repair/Replace Item needs immediate repair or replacement. It is unable to perform its intended function. Not Observed At the time of inspection the item was in a spot that was not accessible or could not be

observed.

Not Present The item was not present/installed at the time of inspection.

#### **General Information**

#### Property Information

Property Address 100 Lemon Peel Way City Anytown State FL. Zip 55555

Agent Name Best Agent

Client Information

Client Name Mr. John Smith

#### **Inspection Company**

Inspector Name Don Pires

Company Name Sterling Home Inspection Services, Inc

Address 4255 US HWY 1 South Suite 18-B11

City St. Augustine State FL Zip 32086

Phone 904-794-2104 Fax 866-645-0704

E-Mail info@shis-inc.com

Conditions

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 6 of 48



## **General Information (Continued)**

Others Present Buyer's Agent and Buyer Property Occupied Vacant Estimated Age 2006 Entrance Faces North
Inspection Date 06/27/2016
Start Time 9:00 am End Time 12:00 pm
Electric On Yes
Gas/Oil On Yes
Water On Yes
Temperature 76 degrees
Weather Clear Soil Conditions Damp
Space Below Grade None
Building Type Single family Garage Detached

#### Roof

Roof Surface -

1. Method of Inspection: On The Roof

2. Not Observed Unable to Inspect: 25% - There were areas of the the roof that were not walk able.

3. Observed Material: Metal



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 7 of 48



# Roof (Continued)

Material: (continued)



4. Type: Gable

5. Approximate Age: Age not verified

6. Observed7. ObservedValleys: Observed

8. Observed Plumbing Vents: Observed

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 8 of 48



# Roof (Continued)

9. Observed - Skylights: Observed - There were repairs noted

around the skylight.



Chimney -

10. Observed Chimney: Observed



11. Observed12. Observed12. Observed13. Chimney Flashing: Observed

### Structure

Observed
 Observed
 Observed
 Observed
 Observed
 Not Observed
 Observed
 Foundation: Observed
 Observed
 Joists/Trusses: Not Observed
 Observed
 Floor/Slab: Observed
 Observed
 Not Observed
 Subfloor: Not Observed


Mr. John Smith 100 Lemon Peel Way Page 9 of 48



# **Lots and Grounds**

1. Recommend Maintenance Driveway: Observed - The driveway has settled and heaved. This is a possible trip

hazard. I recommend contacting a contractor for repair.



2. Recommend Maintenance Walks: Observed - There are bricks have settled. This is a possible trip hazard. I recommend contacting a local landscape contractor for repair. This is a potential safety issue.





11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 10 of 48



# Lots and Grounds (Continued)

Walks: (continued)



3. Observed

4. Repair/Replace

Plantings: Observed

Porch: Observed - There is a missing brick at the column. I recommend contacting a

licensed handyman for repair.





5. Observed6. Observed

7. Observed

8. Observed

9. Observed

10. Observed

Patio: Observed Grading: Observed Balcony: Observed Steps/Stoops: Observed

Deck: Observed

Lawn Sprinklers: All zones were operated - Irrigation systems are typically run through a cycle as a courtesy. I recommend contacting an irrigation company to perform a thorough inspection. Irrigation systems require service. The heads may

require replacing and or adjustment.

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 11 of 48



# Exterior

All Exterior Surface

Observed
 Observed
 Observed
 Observed
 A Observed
 Soffits: Observed

5. Repair/Replace Door Bell: Obsreved - The doorbell is not working. I recommend contacting a licensed handyman for

repair.



6. Observed

7. Observed

8. Repair/Replace

Entry Doors: Observed Patio Door: Observed

Exterior Lighting: Observed - The light fixture was not working at the time of inspection. This may be a burned out bulb. Recommend replacing the bulb and if this does not cure the problem recommend contacting a licensed electrician for repair.



Mr. John Smith 100 Lemon Peel Way Page 12 of 48



# **Exterior (Continued)**

Exterior Lighting: (continued)



9. Repair/Replace

Exterior Electric Outlets: The GFI outlet was not working at the time of inspection. The cover was missing. The moisture cover is missing. I recommend contacting a licensed electrician for repair.





11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 13 of 48



## **Exterior (Continued)**

10. Observed Hose Bibs:

### Garage/Carport

Garage -

1. Type of Structure: Attached Car Spaces: 3

2. Observed
3. Observed
4. Observed
5. Observed
6. Observed
6. Observed
7. Service Doors: Inspected
8. Door Openation: Inspected
9. Door Openation: Inspected
10. Door Openation: Inspected
11. Door Openation: Inspected
12. Door Openation: Inspected
13. Door Openation: Inspected
14. Door Openation: Inspected
15. Observed
16. Observed
17. Door Openation: Inspected
18. Door Openation: Inspected
<li

7. Observed Lighting: Inspected

8. Observed Floor/Foundation: Observed

9. Observed10. ObservedWalls: ObservedCeiling: Observed

11. Observed Windows: Observed - The windows were not inspected. The windows were not

accessible due to the homeowners belongings. I recommend verifying these operate

prior to closing.

### Air Conditioning

Pad Mounted AC System -

1. Observed A/C System Operation: Observed

2. Manufacturer: Lennox





3. Area Served: 1st floor Approximate Age: 2012

4. Type: Heat pump Capacity: 4 Ton

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 14 of 48



# Air Conditioning (Continued)

5. Observed Exterior Unit: Pad mounted



6. Observed
 7. Observed
 8. Observed
 8. Observed
 8. Electrical Disconnect: Observed



9. Observed Interior HVAC unit: Observed



10. Observed Condensate Removal: Observed 11. Observed Float/Pan Switch:

12. Observed A/C System Operation: Observed





11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 15 of 48



# Air Conditioning (Continued)

13. Manufacturer: Lennox

DALLAS, TEXAS INMEXICO

MIN 14HPX — 048 — 230 — 18

SIN 1913F16991

CONTAIN HE — 10A DESIGN PRESSURE
FACTORY CHARGE IN 446 PSIG

LUSTRICA, RG INIC HOMMAL VOLES, 285 285

CONTAINESSOR — 10A MOTOR

PART — 11 IV

TO SIGNATURE — 14 IV

TO SIGNATU

14. Area Served: 2nd floor Approximate Age: 2012

15. Type: Heat pump Capacity: 4 Ton

16. Observed Exterior Unit: Pad mounted



17. Observed Visible Coil: Observed

18. Observed19. Observed19. Electrical Disconnect: Observed



20. Observed Interior HVAC unit:



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 16 of 48



# Air Conditioning (Continued)

21. Electrical Disconnect:
22. Condensate Removal:
23. Float/Pan Switch:

Pad Mounted AC System -

24. Repair/Replace

A/C System Operation: Observed - The AC is not cooling. The minimum temperature differential should be at least 15 degrees. Recommend contacting a local HVAC contractor for repair.



25. Observed Condensate Removal: Observed

26. Repair/Replace Exterior Unit: Pad mounted - The AC is not cooling.

The minimum temperature differential should be at least 15 degrees. I recommend contacting a local

HVAC contractor for repair.



27. Manufacturer: Lennox



28. Area Served: Guest Suite Approximate Age: 2015

29. Type: Heat pump Capacity: 1.5 Ton

30. Observed Visible Coil: Observed

31. Observed Refrigerant Lines: Observed

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 17 of 48



# Air Conditioning (Continued)

32. Observed Electrical Disconnect: Observed



33. Repair/Replace

34. Observed

35. Observed

36. Repair/Replace

Cooling/Heating Temperature: Observed - The AC is not cooling. The minimum temperature differential should be at least 15 degrees. I recommend contacting a local HVAC contractor for repair.

Exposed Ductwork: Observed

Thermostats: Observed

Filters: Observed - The filter is dirty and should be changed. I recommend contacting a licensed handyman to install a new filter. I recommend replacing the

filter as necessary in the future.



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 18 of 48



### **Plumbing**

Not Observed
 Observed
 House Water Shutoff:
 Water Lines: Observed

3. Not Observed Service Caps:

4. Observed Gas Service Lines: Inspected

Laundry Room, Closet Water Heater -

5. Observed Water Heater Operation: Inspected



6. Repair/Replace Tank Condition: Inspected - There is rust at the top of the tank. I recommend contacting a licensed

plumber for further evaluation.



7. Manufacturer: A.O. Smith



8. Type: Electric Capacity: 80 Gallon

9. Approximate Age: 2012 Area Served: Whole building

Mr. John Smith 100 Lemon Peel Way Page 19 of 48



# Plumbing (Continued)

10. Repair/Replace

Plumbing Lines: Observed - There is corrosion at the top of the fittings. I recommend contacting a licensed plumber for further evaluation.







11. Observed

Shut Off: Inspected



**Electrical Connection: Observed** 





11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 20 of 48



# Plumbing (Continued)

13. Observed TPRV and Drain Tube: PVC



Utility Room Water Heater -

14. Observed 15. Observed

Water Heater Operation: Inspected

Tank Condition:



16. Manufacturer: Rheem





17. Type: Electric Capacity: 40 Gal.

18. Approximate Age: 2015 Area Served: Guest Area 19. Observed

Plumbing Lines: Observed



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 21 of 48



# Plumbing (Continued)

20. Observed Shut Off: Observed



21. Observed Electrical Connection: Observed



22. Observed TPRV and Drain Tube: PVC



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 22 of 48



### **Electrical**

Electric Panel

1. Not Observed

Interior Panel Condition: Inspected - The main panel cover because of size was not removed. No action required.







Observed
 Observed

Manufacturer: Square D Main Breaker Size: 600 amp



4. Not Observed5. Observed

Electric Panel -

Conductor Type: Breakers: Observed

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 23 of 48




# Electrical (Continued)

6. Observed Manufacturer: Square D



7. Observed Breakers: Observed



Electric Panel -

8. Observed Manufacturer: Square D



9. Observed Breakers: Observed



Electric Panel -

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 24 of 48



# **Electrical (Continued)**

10. Observed

Manufacturer: Square D





11. Observed

Main Breaker Size: 200 Amps



12. Observed

Breakers:



Electric Panel -

13. Observed

Manufacturer: Square D



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 25 of 48



# Electrical (Continued)

14. Observed Breakers: Observed



Electric Panel

15. Observed







16. Observed

Breakers: Observed



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 26 of 48



#### **Attic**

#### Attic

- 1. Method of Inspection:
- 2. Repair/Replace

Access: Inspected - The pull down steps in the master bedroom is missing appropriate hardware. I recommend contacting a licensed handy man to replace. This is a safety issue.



3. Not Observed

Unable to Inspect: 65% - There is limited access due to the framing and areas that are concealed. All visible areas were inspected. Note: There are two points of access that were not accessible do to the homeowners belongs. No action required this time.



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 27 of 48



# Attic (Continued)

Unable to Inspect: (continued)



4. Observed Roof Framing: Observed

Bathroom Fan Venting: Observed

Vent Pipes: Observed Ventilation: Observed Insulation: Observed Wiring/Lighting: Observed

# Fireplace/Wood Stove

Fireplace '

1. Observed

5. Observed

6. Observed

7. Observed8. Observed

9. Observed

Fireplace Construction: Brick



2. Type: Gas log

3. Not Observed

Fireplace Insert: The fireplace was not inspected. I recommend contacting a local fireplace company to perform a thorough inspection.

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 28 of 48



# Fireplace/Wood Stove (Continued)

4. Not Observed Smoke Chamber:

5. Not Observed Flue: The fireplace was not inspected. I recommend contacting a local chimney

sweep to perform a thorough cleaning and inspection.

6. Not Observed Damper:

7. Observed Hearth: Raised

#### Kitchen

Kitchen -

1. Observed Overview: Observed



2. Repair/Replace

Stove & Oven: DCS - The control panel is not working. There is a missing lens cap on the control knob. I recommend contacting an appliance repair company for repair.



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 29 of 48



# Kitchen (Continued)

Stove & Oven: (continued)



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 30 of 48



# Kitchen (Continued)



4. Observed Wine Cooler: Viking



5. Observed6. Observed7. ObservedVentilator: VentahoodDishwasher: BoschMicrowave: DCS



8. Observed Refrigerator: Sub-Zero



9. Observed Cabinets: Inspected

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 31 of 48



# Kitchen (Continued)

10. Observed Counter Tops: Inspected


11. Observed Electrical: Inspected - The purpose of this switch is unknown. No action required.





12. Observed
13. Observed
14. Observed
15. Observed
16. Observed
17. Observed
18. Disposal: Inspected
19. Disposal: Inspected

16. Repair/Replace Lighting: Observed - The light is. out



17. ObservedPantry: Observed18. ObservedCeiling: Observed19. ObservedWalls: Observed20. ObservedFloor: Observed

21. Doors:

22. Observed Windows: Inspected

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 32 of 48



### **Bathroom**

Bathroom ·

1. Observed

Overview:



2. Repair/Replace

Ceiling: Observed - There is a water stain at the vent and closet ceiling. This may have been caused by the air handler and condensation at the vent. I recommend

monitoring.





3. Observed

4. Observed

5. Observed

6. Not Observed

Walls: Observed Floor: Observed Doors: Inspected

Windows: Inspected - The windows were not inspected due to height. No action required.



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 33 of 48



# Bathroom (Continued)

7. Repair/Replace Lighting: Observed - The light is out. This may be

a burned out bulb. I recommend bulb replacement first. If that does not cure the problem I

recommend contacting a licensed electrician for

repair.



8. Observed Electrical: Inspected

9. Observed Counter/Cabinet: Observed

10. Observed11. Observed12. Observed13. Observed14. Shower/Surround: Observed15. Observed16. Sink/Basin: Observed17. Sink/Basin: Observed18. Shower/Surround: Observed

13. Repair/Replace Spa Tub/Surround: Observed - There is no water

pressure at the tub spout. I recommend contacting

a licensed plumber for repair.



14. Observed15. ObservedVentilation: Observed

Bathroom -

16. Observed Overview:



17. Observed
18. Observed
19. Observed
20. Observed
20. Observed
21. Observed
22. Observed
23. Observed
24. Ceiling: Observed
25. Floor: Observed
26. Doors: Inspected

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 34 of 48



# Bathroom (Continued)

21. Observed Windows: The window is missing the screen. I

recommend contacting a local window company for

replacement.



22. Observed
23. Observed
24. Observed
25. Observed
26. Observed
27. Discreted
28. Electrical: Inspected
29. Sink/Basin: Observed
29. Faucets/Traps: Observed
20. Observed
20. Shower/Surround: Observed

27. Observed Toilets: Observed

Bathroom -

28. Observed Overview:



29. Observed
30. Observed
31. Observed
32. Observed
33. Observed
34. Doors: Inspected

33. Observed Windows: Inspected - The window is missing the

screen. I recommend contacting a local window

company for replacement.



34. Observed35. Observed36. Observed36. Observed37. Sink/Basin: Observed

11:54 November 04, 2016



Mr. John Smith 100 Lemon Peel Way Page 35 of 48

# Bathroom (Continued)

37. Observed Faucets/Traps: Observed

38. Recommend Maintenance Shower/Surround: Observed - The shower door sticks and is difficult to operate. I recommend

contacting a local glass company for repair.



39. Observed Toilets: Observed

Bathroom —

40. Observed Overview:



41. Observed
42. Observed
43. Observed
44. Observed
45. Observed
46. Observed
46. Observed
47. Observed
48. Observed
49. Observed
49. Observed
40. Observed

47. Repair/Replace Lighting: Observed - The light is out.



48. Observed Sink/Basin: Observed 49. Observed Faucets/Traps: Observed

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 36 of 48



### Bathroom (Continued)

50. Repair/Replace Tub/Surround: Observed - There was no water at

the main sower head. I recommend contacting a

licensed plumber for repair.



51. Observed Toilets: Observed 52. Observed Ventilation: Observed

Half Bathroom -

53. Observed Overview: Observed



54. Observed
55. Observed
56. Observed
57. Observed
58. Observed
59. Observed
60. Observed
Ceiling: Observed
Walls: Observed
Floor: Observed
Doors: Inspected
Electrical: Inspected
Lighting: Observed
Sink/Basin: Observed

61. Repair/Replace Faucets/Traps: Observed - There is a broken stop

and mechanism. I recommend contacting a licensed

plumber for repair.



62. Observed
63. Observed
Ventilation: Observed

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 37 of 48



## Bathroom (Continued)

Half Bathroom -

64. Observed

Overview:



65. Observed
66. Observed
67. Observed
68. Observed
69. Observed
69. Observed
65. Ceiling: Observed
Walls: Observed
Floor: Observed
Doors: Inspected
Windows: Inspected

70. Repair/Replace Electrical: Inspected - The ground fault outlet is not working. I recommend contacting a licensed

electrician for repair.



71. Repair/Replace

72. Observed

73. Observed

Lighting The lights are out.



Sink/Basin: Observed Faucets/Traps: Observed

74. Observed Toilets: Observed



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 38 of 48



#### Bathroom (Continued)

75. Repair/Replace

Ventilation: The vent fan is not working. I recommend contacting a licensed electrician for repair.



#### **Bedroom**

Bedroom -

1. Observed

Overview:



2. Observed

Closet: Observed - There is an old water stain. It does not appear this is an ongoing leak. Recommend painting with a stain blocker such as Bin or Kilz and monitoring to verify that it does not appear prior to finish painting.



3. Observed
4. Observed
5. Observed
6. Observed
7. Observed
Ceiling: Observed
Walls: Observed
Floor: Observed
Doors: Inspected

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 39 of 48



#### **Bedroom (Continued)**

8. Not Observed

Windows: Inspected - The windows were not inspected due to height. No action

required.





9. Observed

Electrical: Inspected - The purpose of this switch is unknown. No action required.





Bedroom -

10. Observed

Overview:



11. Observed
12. Observed
13. Observed
14. Observed
15. Observed
16. Observed
17. Observed
18. Closet: Observed
19. Ceiling: Observed
19. Lighting: Inspected
19. Walls: Observed
19. Cobserved
19. Cobserved
19. Closet: Observed
19. Cobserved
19. Cobserved
19. Cobserved
19. Closet: Observed

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 40 of 48



### Bedroom (Continued)

18. Observed

Electrical: Inspected - There may be concealed outlets that were not inspected due

to the homeowners belongings. No action required at this time.





Bedroom -

19. Observed

Overview:



20. Observed
21. Observed
22. Observed
23. Observed
24. Observed
25. Observed
26. Observed
27. Observed
28. Observed
29. Observed
20. O

26. Repair/Replace Windows: Inspected - The crank mechanism is

stripped. I recommend contacting a licensed

handyman for repair.



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 41 of 48



#### Bedroom (Continued)

27. Observed

Electrical: Inspected - There may be concealed outlets that were not inspected due to the homeowners belongings. No action required at this time.





#### **Living Space**

Living Space

1. Observed Overview:



Observed
 Observed

4. Repair/Replace

Closet: Observed Ceiling: Observed

Lighting: Observed - The light fixture does not work. This may be a burned out bulb. Recommend replacing the bulbs. If this does not cure the problem recommend

contacting a licensed electrician for repair.





5. Observed6. Observed7. Observed

Walls: Observed Windows: Inspected Floor: Observed

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 42 of 48



## **Living Space (Continued)**

8. Observed Doors: Inspected 9. Observed Electrical: Inspected

Living Space - 10. Observed

Overview:



11. Not Observed Closet: Observed - The closet was not fully

inspected due to the homeowners belongings. No

action required.



12. Observed
13. Observed
14. Observed
15. Observed
16. Observed
16. Observed
17. Observed
18. Observed
19. Ceiling: Observed
19. Walls: Observed
19. Floor: Observed
19. Electrical: Inspected

Living Space -

17. Observed Overview:



18. Observed Ceiling: Observed

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 43 of 48



## Living Space (Continued)

19. Repair/Replace Lighting: Inspected - The ceiling light is out.



20. Observed
21. Observed
22. Observed
23. Observed
24. Windows: Inspected
25. Electrical: Inspected

Living Space 24. Observed

Overview:



25. Observed
26. Observed
27. Observed
28. Observed
28. Observed
29. Observed
20. Ceiling: Observed
Lighting: Inspected
Walls: Observed
Floor: Observed

29. Recommend Maintenance Windows: Inspected - The handle is loose. I recommend contacting a licensed

handyman for repair.





30. Observed Electrical: Inspected

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 44 of 48



## Living Space (Continued)

Living Space

31. Observed

Overview:



32. Observed
33. Observed
Walls: Observed
34. Observed
Floor: Observed

35. Not Observed Windows: Not Inspected - The windows were not

inspected due to height. No action required.



36. Observed Electrical: Inspected - The purpose of this switch is unknown. No action required.



37. Repair/Replace Lighting: Observed - The light is out.

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 45 of 48



# Living Space (Continued)

Lighting: (continued)



Living Space 38. Observed

Overview:



39. Observed
40. Observed
41. Observed
42. Observed
43. Observed
44. Observed
44. Observed
45. Observed
46. Observed
47. Observed
48. Observed
49. Observed

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 46 of 48



# Living Space (Continued)

45. Observed

Electrical: Inspected





46. Repair/Replace

Plumbing: The disposal does not work. I recommend contacting a licensed plumber for repair.



Living Space

47. Observed

Overview:



48. Observed
49. Observed
50. Observed
51. Observed
Doors: Inspected

11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 47 of 48



### Living Space (Continued)

52. Repair/Replace

Lighting: Inspected - The light is out.



53. Repair/Replace Windows: Inspected - The crank mechanism is stripped. I recommend contacting a

licensed handyman for repair.

The window is missing the screen. I recommend contacting a local window company

for replacement.

54. Observed Electrical: Inspected

#### Laundry Room/Area

Laundry Room/Area -

1. Observed Overview:



2. Observed3. Observed4. Observed5. Ceiling: Observed6. Walls: Observed7. Floor: Observed

5. Repair/Replace Doors: Inspected - The door latch is not engaging. I recommend contacting a

licensed handyman for repair.



11:54 November 04, 2016

Mr. John Smith 100 Lemon Peel Way Page 48 of 48



#### Laundry Room/Area (Continued)

6. Observed7. ObservedWindows: InspectedElectrical: Inspected

8. Observed9. ObservedWasher & Dryer Operation ObservedWasher and Dryer Electrical: Observed

10. Observed Washer Hose Bib: Observed

11. Observed Dryer Vent: Observed - The dryer vent because of it's location (inside wall) travels

vertical before exiting the home. This method is more likely to have a build up of lint. This can cause inefficiency if not properly maintained. I recommend contacting a

This can cause inemciency if not properly maintained. Trecommend conta

local dryer vent company to perform regular cleaning.

12. Observed Washer Drain: Observed

#### **Final Comments**

Smoke detectors, fireplaces, wood stoves, outbuildings, wells and septic systems are not inspected.